



104.08.06-08.09 蘇迪勒颱風 專案報告

國立中山大學總務處


104.8.6 14:00召開防颱會議
104.8.7 19:50召開颱風應變會議



104.8.8 06:30搶通往文學院道路




104.8.8 海科院路樹倒塌(1/2)



104.8.8 海科院路樹倒塌(2/2)



104.8.8 09:20疏通大排水溝之淤泥浮木



疏通大排水溝之淤泥浮木，避免堵塞出水口


104.8.8 10:00校長親臨防颱指揮中心
聽取黃總務長簡報

The left photograph shows a group of men in a room with a large window and a fan. One man in a yellow shirt and blue vest is pointing towards the window. The right photograph shows two men in yellow shirts and blue vests, one holding a white hard hat. Both photographs have a date stamp '2015 08 08' in the bottom right corner.



體育哨周邊、西子樓損害情形

體育哨周邊



體育哨周邊

西子樓



西子樓

國研大樓、蔣公行館、武嶺宿舍、教職員宿舍樹木損害情形



清除教職員宿舍之倒塌殘樹



L棟宿舍前方樹木倒塌



清除L棟宿舍前方倒塌路樹



104.8.9凌晨 L棟及翠亨宿舍前方樹木倒塌(1/2)



104.8.9凌晨 L棟及翠亨宿舍前方樹木倒塌(2/2)



104.8.9凌晨 翠亨道樹木倒塌

